## APPENDIX C INVENTORY OF DOCUMENTATION AND REFERENCE DOCUMENTS

## <u>Document List – Stone Industrial</u>

April 10, 1981	Letter indicating revised quantities and materials
T1 14 1001	I was a second of Constitution of Constitution Desired Later in Constitution Consti
July 14, 1981	Letter regarding Conditions of Operation During Interim Status
February 23, 1982	US EPA Region III Hazardous Waste Report
June 10, 1982	US EPA Region III RCRA Inspection Summary
June 10, 1902	US EFA Region III RCRA inspection Summary
July 20, 1982	US EPA Region III RCRA Inspection Summary
September 26, 1983	Letter from Department of Health and Hygiene regarding withdrawal of permit application
January 19, 1984	Letter regarding 90-day storage
March 22, 1984	Hazardous Waste Monitoring and Enforcement Log
April 17, 1986	Letter regarding facility equipment locations
February 2, 1988	Letter from Stone Industrial indicating name change
April 1, 1988	RCRA Inspection Report
May 3, 1988	RCRA Inspection Report
July 19, 1988	Notice indicating Interim Status withdrawn by Maryland
October 1989	Environmental Priorities Initiative Preliminary Assessment of Stone Industrial
October 9, 1989	Letter to MDE regarding MEK release
September 28, 1990	Addendum to Environmental Priorities Initiative Preliminary Assessment Reports
March 22, 1993	Letter regarding removal of 6 USTs
March 11, 1994	Letter regarding malfunction of Regenerative Thermal Oxidizer
April 7, 1994	Site Complaint
April 25, 1994	Letter regarding malfunction of Regenerative Thermal Oxidizer

May 24, 1994	Letter regarding malfunction of Regenerative Thermal Oxidizer
111uy 24, 1994	Letter regarding manufaction of Regenerative Thermal Oxidizer
0.4.12.1004	I " I' IC " CD " TI IO"I
October 3, 1994	Letter regarding malfunction of Regenerative Thermal Oxidizer
December 13, 1994	Letter regarding malfunction of Regenerative Thermal Oxidizer
1995	Updated Site Layout Plan
1336	opation Site Enjour Fran
A	I - 11 - 11 - 11 - 11 - 11 - 11 - 11 -
April 28, 1995	Letter regarding malfunction of Regenerative Thermal Oxidizer
May 22, 1996	Letter regarding malfunction of Regenerative Thermal Oxidizer
May 2, 1997	Letter regarding previous removal of USTs
,	
June 15, 1999	Letter regarding Permit to Construct Four Spiral Tube Winders
June 13, 1777	Letter regulating remit to construct rour opilar rube winders
D 12 1000	I " I' E ' ' C ('C' (' C 1000
<b>December 13, 1999</b>	Letter regarding Emission Certification for 1999
August 3, 2000	MDE Report of Observations
September 5, 2000	Correspondence Regarding Secondary Containment for Drums
January 15, 2002	Correspondence Containing Contingency Plan for Emergency
January 13, 2002	Response Procedures
	Response Frocedures
1 1 1 6 200	MOREWALL
August 16, 2007	MDE Waste Management Administration Inspection Report
<b>April 28, 2009</b>	Air and Radiation Management Administration – Inspection and
	Observation Report
	•
June 1, 2009	Operating Permit under Air and Radiation Management
Guile 1, 2007	Administration
	Administration
T 0< 0040	WY
<b>January 26, 2010</b>	Wastewater Manifest